


MHHS System Integration Test Scenarios/Cases Release Note 04-04-2025



Document owner

SIT Test Team

Status:

Final

Document number

MHHS-DEL3614

Date

04/04/2025

Version

1.0

Classification

Public

1 Table of Contents

1	Table of Contents	2
1.1	Change Record	3
1.2	Reviewers	3
2	Introduction	4
3	Overview	4
4	New and Changed Test Cases to Address Coverage Gaps.....	5
5	Defect Fixes.....	6
6	Test Case Updates.....	7

1.1 Change Record

Date	Author	Version	Change Detail
02/04/2025	Izhan Ahsan	1.0	First issue

1.2 Reviewers

Reviewer	Role

2 Introduction

These are the release notes for updates to the MHHS System Integration Testing Functional Test Scenarios and Test cases for Cycle 3 SIT Functional test execution.

3 Overview

This document communicates changes to previously issued content to address:

1. Coverage gaps mitigation; including existing IR7 gaps and new IR8 design baseline changes.
2. Test case defects raised during SIT Functional test execution.
3. Technical updates to test cases that have been made since the previous release.

4 New and Changed Test Cases to Address Coverage Gaps

This section identifies test cases created or updated to assure requirements coverage. Redlined versions are included for all changed Test Cases.

Theme	Scenario Filename	Scope Summary	New/Changed
3 – Change of Supplier	MHHS-DEL1813 SITFTS-0010 COS v0.6.6	TC01 (v0.6.6) Updated to map Requirement MHHSP-BRS014-ECS-BR-RD-001 to Test Step 49.	Changed
6 – Metering Changes	MHHS-DEL1887 SITFTS-0280 – MET Energisation Change v0.6.8	TC01 (v0.6.4) Updated to map Requirement MHHSP-BRS014-ECS-BR-RD-001 to Test Steps 17 and 18.	Changed
6 – Metering Changes	MHHS-DEL1894 SITFTS-0900 – MET Change of Meter successful v0.8.7	TC01 (v0.8.4) Updated to map Requirement MHHSP-BRS014-ECS-BR-RD-001 to Test Step 22.	Changed
6 – Metering Changes	MHHS-DEL1890 SITFTS-0845 MET Supp Disc De-Energise during COS v0.6.6	TC01 (v0.6.6) Updated to map Requirement MHHSP-BRS014-ECS-BR-RD-001 to Test Steps 92, 108 and 109.	Changed
2 – Change of Registration	MHHS-DEL1764 SITFTS-0940 REG UPD Domestic Premise Indicator v0.5	TC01 (v0.5) mapped to requirement MHHSP-BRS014-ECS-BR-RD-001 to Test Step 50.	Changed
2 – Change of Registration	MHHS-DEL1770 SITFTS-0990 REG UPD SMSO v.0.4.3	TC01 (v0.4.3) Updated to map Requirement MHHSP-BRS014-ECS-BR-RD-001 to Test Step 8.	Changed
1 – New Connection	MHHS-DEL1757 SITFTS-0050 New Connection v0.8.9	TC01 (v0.9) Updated to map Requirement MHHSP-BRS014-ECS-BR-RD-001 to Test Steps 106 and 107.	Changed
2 – Change of Registration	MHHS-DEL1806 SITFTS-0100 REG Change Cust MS Appt v0.6.9 (redlined)	TC01 (v0.6.5) Updated to map Requirement MHHSP-BRS014-ECS-BR-RD-001 to Test Step 8.	Changed

5 Defect Fixes

This section identifies test case changes triggered by queries or defects raised in Cycle 2 SIT Functional test execution.

Note: Redlined versions are also included in this upload for all files listed below.

Scenarios and Test Cases:

Theme	Scenario Filename	Scope Summary
7 - Consumption	MHHS-DEL1937 SITFTS-0012 CONS COS Transfer of Reads v0.7	50972: TC01 (v0.6.5) updated to remove test step 7 (LDSO receives D0010 from SUPO). This test step is incorrect as there is no such interface between SUPO and LDSO.
6 – Metering Changes	MHHS-DEL1916 SITFTS-0860 MET Change of Market Segment v0.6.9	48293: Updated TC05 & TC06 with de appointment and appointment steps prior to Linkage and Relating. Second set of IF-037/PUB-037 IF-036/PUB-036 set as optional after the Linkage and Relating dependent on what service is appointed prior to Linkage and Relating (if a different service is appointed prior to Linkage and Relating auto re alignment rules will apply) 50919, 50971: Re added in Metering Service and Data Service to receive PUB-020 on TC05 & TC06. 50971 is related to TC06 only
6 – Metering Changes	MHHS-DEL1918 SITFTS-0870 MET Connect Type Change (MS) v0.6.1	50562: Removed reference to D0268 and D0010 on TC01 design team have confirmed that on a market segment change that information would be sent on an IF-041/PUB-041 Meter removes event code
5 – Change of Metering Service	MHHS-DEL1810 SITFTS-0120 MS DS Change v0.5.8	50858: Amended TC02, TC03 & TC06 to better represent send MTD IF-035/PUB-035 is issued by whoever is the current incumbent meter service at that time
2 – Change of Registration	MHHS-DEL1772 SITFTS-1000 REG UPD Linked v0.2.4	51344: Removed D0149/D0150 on TC04 and D0268 on TC05 MTD's would not be issued on auto re alignment
5 – Change of Metering Service	MHHS-DEL1807 SITFTS-0105 MS Change during COS v0.6.6	51733: Re sequenced test step numbering on TC01, TC02 & TC03 as it was misaligned

6 Test Case Updates

This section identifies any technical changes that have been made to test cases since the previous release.

Theme	Scenario Filename	Scope Summary	New/Changed
6 - Metering Changes	MHHS-DEL1890 SITFTS-0845 MET Supp Disc De-Energise during COS v0.6.6	TC03 (v0.6.7) updated to correct Service Recipient on Step 119 of test case SITFTS-0845 TC03 to EES.	Changed
2 – Change of Registration	MHHS-DEL1766 SITFTS-0960 REG UPD Related v0.5.4	TC01 (v0.5.4) updated to remove test step 10 (MDS receives PUB-020 with confirmation of the unrelating of MPANS). This routing was removed from DIP as part of DIN-468. TC02 (v0.5.3) updated to remove test step 10 (MDS receives PUB-020 with confirmation of the relating of MPANS). This routing was removed from DIP as part of DIN-468.	Changed
8 - Settlements	MHHS-DEL2146 SITFTS-ST0040 COS MS DS Change v7.2	TC01 (v7.2) TC02 (v7.2), TC03 (v7.2) and TC04 (v7.2) have been updated to accommodate the revised run chronology required for the forthcoming test executions	Changed
8 - Settlements	MHHS-DEL2163 SITFTS-ST0032 Settling Clock Changes v0.8.5	TC09 (v0.8.2) amended to reflect the execution of this test case in SITA (reduced Data requirements, Helix to undertake LDSO report checks, REP-002B introduced (erroneously excluded previously)).	Changed
8 - Settlements	MHHS-DEL2152 SITFTS-ST0070 LSS Reject and Default v0.8.5	TC04 (v0.8.4) updated to remove '= E' from Step 10. This was not removed when the TC was last updated and has been uploaded to ADO as '= E', which is incorrect.	Changed
7 - Consumption	MHHS-DEL1937 SITFTS-0012 CONS COS Transfer of Reads v0.7	TC01 (v0.6.5) updated to remove test step 7 (LDSO receives D0010 from SUPO). This test step is incorrect as there is no such interface between SUPO and LDSO.	Changed